Approved For Release 2006/10/18 : CIA-RDP89B00569R000500130061-5

CLASSIFIED MESSAGE

~~TOP SECRET~~
TOPSECRET

ROUTING

1		4	
2		5	
3		6	

DATE 1931Z 15 NOV 61

OPERATIONAL IMMEDIATE

TO : DIRECTOR

FROM : [redacted] 25X1

ACTION: OPS (1-2-3-~~4~~-5)

OPERATIONAL IMMEDIATE

INFO : S/C (6)

WLM

TOR: 1915Z 15 NOV 61

IN 22555

25X1

[redacted] INFO [redacted] 25X1 CITE [redacted] 9167

25X1

A. 1082.

25X1 B. [redacted] /1853Z.

C. GOOD.

D. GOOD.

E. AC ALTERNATOR FAILURE.

F. NONE.

G. A/C ALTERNATOR FAILED. PILOT OBSERVED SMOKE FROM ENGINE AREA VENTS. BELIEVED CAUSED FROM ALTERNATOR FAILURE. PRELIMINARY INSPECTION IN WHEEL WELL INDICATES A/C ALTERNATOR WIRING CHARRED. WILL ADVISE FURTHER DETAILS WHEN AVAILABLE. [redacted] ENGINEER INVESTIGATING PROBLEM.

25X1

END OF MESSAGE

DOCUMENT NO. _____
NO CHANGE IN CLASS. ☐
☐ DECLASSIFIED
CLASS. CHANGED TO: TS (S) C
NEXT REVIEW DATE: _____
AUTH: HR 70-2
DATE: 25 Sept 86 REVIEWER: [redacted]

25X1

~~TOP SECRET~~
TOPSECRET

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

Approved For Release 2006/10/18 : CIA-RDP89B00569R000500130061-5